# Weathertzation Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/Client 50005DE0058/1

Work Order Type: Weatherization Audit Name: Audit DE0058

**CLIENT INFORMATION** 

Client Name: Address:

Client ID: Client 50005DE0058

Alt. Client ID:

<u>AGENCY INFORMATION</u>

**Agency:** 50005DE **Agency Phone:** (901) 476-5226

**Address:** P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

**Email Address:** 

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

House was built in 1955 - Has possible Lead based paint and has Asbestos siding

Alt. Client ID:

### **Measures**

Comment	Measure 1 Build crawl space access with latch			Componen	ts		ı	nspecte
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
			Moasur	re Sub Total:		]]	Sub Total:	
Field Notes:			IVICASUI	e Sub Total.		]	oub rotar.	
_	pair Attic Stairs			Componen				Inspecte
Comment		Unite	Oftv	Estimated	1	Oftv	Actual	
Comment # Material / Labor	Description / Comment Material	<i>Units</i> Each	<b>Qty</b> 1	-		Qty		Total
# Material / Labor  1 Other	Description / Comment		_	Estimated	1	Qty	Actual	
# Material / Labor  1 Other  2 Labor	Description / Comment  Material	Each	1	Estimated	1	Qty	Actual	
# Material / Labor  1 Other	Description / Comment  Material	Each	1	Estimated	1	Qty	Actual	
# Material / Labor  1 Other  2 Labor	Description / Comment  Material	Each	1	Estimated	1	Qty	Actual	
# Material / Labor  1 Other  2 Labor	Description / Comment  Material	Each Each	1 1	Estimated	1		Actual	
# Material / Labor  1 Other  2 Labor  Other Detail	Description / Comment  Material	Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor  1 Other  2 Labor	Description / Comment  Material	Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/23/2010

	1. Air S 2. Wea 3. Add 4. Repl	FILTRATION MEASURES eal Plumbing penetration therstrip Doors - Front an Thresholds - Front and Si ace Broken Panes W3, W eal all Boots with Mastic S  Description / Comment	s nd Side - A ide V5			l	Qty	Actual Unit Cost	Total
10	Miscellaneous	Infiltration Reduction	Each	1					
_	Supplies								
<b>C</b>	Other Detail								
_				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
		H Pipe Insulation			Componen				Inspected
C	Measure 4 DW		Units	Qty	Component  Estimated  Unit Cost		Qty	Actual Unit Cost	Inspected Total
C	Measure 4 DW omment Material / Labor	H Pipe Insulation  Description / Comment  DHW Pipe Insulation	<i>Units</i> Each	<b>Qty</b> 1	Estimated	<u> </u>	Qty	Actual	
<b>C</b> #	Measure 4 DW omment Material / Labor	Description / Comment			Estimated	<u> </u>	Qty	Actual	
<b>c</b> # 1	Measure 4 DW omment  Material / Labor Insulation	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
<b>c</b> # 1	Measure 4 DW omment  Material / Labor Insulation Labor	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
<b>c</b> # 1	Measure 4 DW omment  Material / Labor Insulation Labor	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	<u> </u>		Actual Unit Cost	
<b>c</b> # 1	Measure 4 DW omment  Material / Labor Insulation Labor	Description / Comment  DHW Pipe Insulation	Each	1 1	Estimated	<u> </u>		Actual	

**Components** 

Inspected

**Measure 3** Infiltration Redctn

Report Run On: 5/23/2010

Measure 5 Flo	or Ins. R-19			Componen	ts crawl	- 936 st	f /	nspecte
Comment								
				Estimated	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	936					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Field Notes:								
Field Notes:								
Field Notes:  Measure 6 Atti	c Ins. R-38			Componen	<b>ts</b> 936 so	- γ.ft		nspecte
Measure 6 Atti	<b>c Ins. R-38</b> wner must remove storag	e - before	· addin	•	<b>ts</b> 936 so	ft.ft		nspecte
Measure 6 Atti		e - before	addin	•		դ.ft 	I Actual	nspecte
Measure 6 Atti Comment Homeo		e - before <i>Unit</i> s	adding	g insulation		q.ft		nspecte 
Measure 6 Atti Comment Homeo # Material / Labor	wner must remove storag			g insulation Estimated	1		Actual	
Measure 6 Atti Comment Homeo # Material / Labor	wner must remove storag  **Description / Comment**  Attic Insulation - Blown	Units	Qty	g insulation Estimated	1		Actual	
Measure 6 Atti Comment Homeo # Material / Labor 1 Insulation	wner must remove storag  **Description / Comment**  Attic Insulation - Blown	Units	Qty	g insulation Estimated	1		Actual	
Measure 6 Atti Comment Homeo # Material / Labor 1 Insulation	wner must remove storag  **Description / Comment**  Attic Insulation - Blown	Units	Qty	g insulation Estimated	1		Actual	
Measure 6 Atti Comment Homeo # Material / Labor 1 Insulation	wner must remove storag  **Description / Comment**  Attic Insulation - Blown	Units SqFt	<b>Qty</b> 936	g insulation Estimated	1	Qty	Actual	

Measure 7 Ref	rigerator Rplcmnt			Componen	its			Inspected
<b>Comment</b> Fridge	leaking on inside - Recom	nmend rep	lacing					
				Estimated	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Refrigerators	-	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Magazira 9 Film	mana Tunaun			Componen	140			Inspected
Measure 8 Fur	nace runeup			Componen	its			mspecieu
Comment					_			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating	Furnace Tuneup	Each	1					
Equipment								
2 Labor	Furnace Tuneup	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
10.0.100								

Report Run On: 5/23/2010

Measure 9 CO	Monitor is Needed			Componen	ts		ı	Inspected
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Moasur	e Sub Total:		] []	Sub Total:	
Field Notes:			INCASUI	e Sub Total.		]		
•	or Barrier Needed ement/CrawIspace) arrier must cover enitre a	area and e	xtend (	-	ılls			Inspected
#				Estimated			Actual	
<ul><li># Material / Labor</li><li>1 Health and Safety Items</li></ul>	Description / Comment  Basement / crawlspace vapor barrier	<b>Units</b> Each	<b>Qty</b> 1	Unit Cost	Total	Qty	Unit Cost	Total
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work O	rder Gra	and Total:		Gran	d Total:	